
HANDLE INSTALLATION

Rotationally Molded Tanks Blow Molded Tanks





- Place washer (A) and gasket (828980) onto screw (712541) and slide screw through tank and handle. Screw weldnut (711444PLT) onto screw, while tightening weldnut and screw - make sure that weldnut stays in vertical position during tightening (smooth surface of weldnut facing out).
- 2. Screw acorn nut (711352) onto remaining thread and tighten with 7/16" wrench.

Tools: Phillips screwdriver or screw gun w/Phillips bit and 7/16" wrench